

## PRE-REAM DRILL SIZE TABLE FOR REAMING

Material	Ø up to 6 mm	Ø up to 10 mm	Ø up to 16 mm	Ø up to 25 mm	Ø over 25 mm
Steels up to 700 N/mm <sup>2</sup>	0,1 - 0,2	0,2	0,2 - 0,3	0,3 - 0,4	0,4
Steels 700 - 1000 N/mm²	0,1 - 0,2	0,2	0,2	0,3	0,3 - 0,4
Cast steel	0,1 - 0,2	0,2	0,2	0,2 - 0,3	0,3 - 0,4
Cast iron GG	0,1 - 0,2	0,2	0,2 - 0,3	0,3 - 0,4	0,3 - 0,4
Cast iron GGG	0,1 - 0,2	0,2	0,3	0,3 - 0,4	0,4
Copper	0,1 - 0,2	0,2 - 0,3	0,3 - 0,4	0,4	0,4 - 0,5
Brass - Bronze	0,1 - 0,2	0,2	0,2 - 0,3	0,3	0,3 - 0,4
Light alloys	0,1 - 0,2	0,2 - 0,3	0,3 - 0,4	0,4	0,4 - 0,5
Plastics, hard	0,1 - 0,2	0,2	0,4	0,4 - 0,5	0,5
Plastics, soft	0,1 - 0,2	0,2	0,2	0,3	0,3 - 0,4

Stock allowance (recommended values in mm)

Due to the efficient action of the spiral, the values for quick spiral reamers may be increased by 50 to 100%.





## **APPLICATION INDICATIONS AND SOLUTIONS FOR REAMING**

Problem	Cause	Solution	
Diameter is too large	<ul> <li>Cutting speed is too high</li> <li>Feed rate is too high</li> <li>Insufficient lubricating coolant delivery</li> <li>Incorrect lubricating coolant composition</li> <li>Point is too short or very uneven</li> <li>Tool or machine spindle rotation incorrect</li> <li>Due to low-density or flexible structure, the working material enlarges</li> </ul>	Reduce cutting speed Reduce feed rate Ensure good lubricating coolant delivery Ensure correct lubricating coolant composition Lengthen point or reduce point angle Centrally clamp or guide the reamer. Use a reamer chuck Reduce reamer diameter	
Diameter is too narrow	<ul> <li>Cutting speed is too low</li> <li>Feed rate is too low</li> <li>Chip removal rate is too low</li> <li>Point is too long</li> <li>Tool is ground smooth</li> <li>The working material is of high density or has an inflexible structure</li> <li>Reamer of insufficient size</li> <li>Too much heat created when reaming. Shrinking borehole</li> <li>Tool diameter too small</li> </ul>	Increase cutting speed Increase feed rate Increase machining allowance Select a smaller point Check the tool and replace in good time Increase reamer diameter Select a higher allowance Increase lubricating coolant delivery Select the correct diameter	
Heavy wear	Insufficient size	Select a larger diameter	
Borehole is not round or is conical	<ul> <li>Incorrect positioning in the machine spindle</li> <li>Alignment error between the tool and the borehole</li> <li>Asymmetrical point angle</li> <li>Incorrect tool run-out</li> <li>Clearance angle too great</li> <li>Point is not round</li> <li>Insufficient guide</li> </ul>	Check the spindle and correct its position Use front-cutting reamers Re-sharpen point angle Centrally clamp tool, use reamer chuck and guide Reduce clearance angle when re-sharpening Evenly sharpen and round the point	
Poor surface quality	Worn tool     Front rake angle is too small     Cutting speed is too low     Feed rate is too low     Workpiece tends to stick (built-up edge)     Cutting exit is sharp-edged     Insufficient lubricating coolant delivery     Incorrect lubricating coolant composition     Cutting is uneven     Defective point	<ul> <li>Replace or re-sharpen tool in good time</li> <li>Re-sharpen correctly</li> <li>Increase cutting speed</li> <li>Increase feed rate</li> <li>Increase clearance angle and front rake angle; use highly fluid lubricant</li> <li>Round and smooth the borehole exit</li> <li>Ensure good lubricating coolant delivery</li> <li>Ensure correct lubricating coolant composition</li> <li>Grind the point and guide piece to an evenly round shape or to a tapered shape</li> <li>Finely smooth or lap the point round and smooth the guide piece joint</li> </ul>	
The tool jams and breaks	<ul><li>Borehole is too narrow</li><li>Bevel width is too great</li><li>Shaft is too short</li><li>Worn tool</li></ul>	Reduce material cross-section     Check the tool and replace if necessary     Check the tool and replace if necessary     Replace or re-sharpen tool in good time	
Borehole exit too narrow	Feed rate when removing the reamer from the borehole is too high	Reduce feed rate shortly before passing through or use even feed rate	
Broken off or deformed driver	Incorrect position between shaft and clamping device	Keep shaft and clamping device clean and undamaged	



