

## MANUFACTURING TOLERANCES FOR ENDMILLS

	Tolerance d1 (mm)			Tolerance precision Ball Nose (mm)			Tolerance standard Ball Nose(mm)			Tolerance d2 (shank)
Ø	0,5 5,0	6,0 12,0	16,0 20,0	Rad. 0,5 1,25	Rad. 1,50 3,00	Rad. 4,00 6,00	Rad. 0,5 2,50	Rad. 3,00 6,00	Rad. 8,00 10,00	0,5 20,0
Serie 90	+ 0,000 - 0,01	- 0,01 - 0,025	- 0,015 - 0,03	-	-	-	+/- 0,005	+/-0,01	+/- 0,015	
Serie 91				-	-	-				
Serie 92				+/- 0,005	+/- 0,007	+/-0,01	-	-	-	
Serie 93							-	-	-	h6
Serie 94				-	-	-	+/- 0,005	+/-0,01	+/- 0,015	
Serie 96	+ 0,000 / -0,02		-	-	-	-	-	-	-	






## TROCHOIDAL SYSTEM

Trochoidal Speed Cutting System is a new machining cycle which combines circular milling with a forward moving. Thereby, huge cross-sections can be processed with low cutting forces and high speeds.

ae: width of cut

**aeff:** effective width of cut **W:** Bore diameter / slot width **a:** angle of cutting bow



Circular milling vs. Full-slot milling





## APPLICATION INDICATIONS AND SOLUTIONS FOR MILLING

Problem	Cause	Solution			
Vibrations on the milling cutter	<ul> <li>Cutting speed is too high</li> <li>Feed rate is too low</li> <li>Tool clamping is not unstable</li> <li>Tool is too long</li> <li>Tool is too unstable</li> <li>Flute length too great</li> </ul>	Reduce cutting speed Increase feed rate Check the clamping device or replace If possible, choose the quickest possible process Use a stronger shaft If possible, choose the quickest possible process			
Vibrations on the workpiece	Clamping is not stable enough	Check tool clamping and optimize if appropriate			
Cutter breakage	<ul> <li>Tool wear</li> <li>Incorrect cutting specifications</li> <li>Vibrations</li> <li>Conventional milling</li> <li>Tool stability</li> <li>Workpiece stability</li> </ul>	Replace or re-sharpen tool in good time Match cutting specifications to the work Reduce rotation speed Mill in synchronism If possible, choose the quickest possible process Check clamping device and optimize if appropriate			
Breakage of the cutting edge	Tool stability Workpiece stability Vibrations Feed rate is too high Conventional milling Cutting material too brittle Incorrect tool	If possible, choose the quickest possible process Check clamping device and optimize if necessary Reduce rotation speed Reduce feed rate Mill in synchronism Replace with a tool made from a higher quality cutting material Select the tool according to the work			
Milled slot is too small less than the diameter of the tool	Too much tool wear	Replace or re-sharpen tool in good time			
Milled slot is too large less than the diameter of the tool	• Tool run-out error	Minimize run-out error			
Service life is too short	Reaming is too intense Incorrect tool chosen Incorrect front rake angle Lip clearance of the tool is incorrect	Use a coated tool Adjust tool to the work Select a tool with the correct front rake angle Correctly grind or re-sharpen the tool			



